

# MS SW シングルダブル軸穴加工付スプロケット

横軸＝内径  
縦軸＝歯数

MS40SW

	15	18	20	25	28	30	35	
12	○	○						
13		○	○					
14		○	○					
15			○	○				
16			○	○				
17				○	○	○		
18				○	○	○	○	
19				○	○	○	○	
20				○	○	○	○	
21				○	○	○	○	

MS50SW

	18	20	25	28	30	35	40	
12	○	○						
13		○	○					
14		○	○	○				
15		○	○	○	○			
16			○	○	○	○		
17			○	○	○	○	○	
18			○	○	○	○	○	
19			○	○	○	○	○	
20			○	○	○	○	○	
21			○	○	○	○	○	

MS60SW

	20	25	30	35	40	45	50	
12	○	○	○					
13		○	○	○				
14		○	○	○	○			
15			○	○	○	○		
16			○	○	○	○	○	
17			○	○	○	○	○	
18			○	○	○	○	○	
19				○	○	○	○	○
20				○	○	○	○	○
21				○	○	○	○	○

MS80SW

	35	40	45	50	60			
12	○	○	○					
13		○	○	○				
14		○	○	○	○			
15		○	○	○	○			
16		○	○	○	○	○		
17		○	○	○	○	○		
18		○	○	○	○	○		
19		○	○	○	○	○		
20		○	○	○	○	○		
21		○	○	○	○	○		

# SMS ステンレス軸穴加工付スプロケット

SMS25

	10	12	15						
16	○								
17	○								
18	○								
19	○	○							
20	○	○							
21	○	○							
22	○	○							
23	○	○							
24	○	○							
25	○	○							
26	○	○							
27	○	○							
28	○	○							
30	○	○							
32	○	○							

SMS35

	10	12	15	16	18	20	22	25	30		
10	○	○									
11	○	○									
12	○	○	○								
13	○	○	○	○							
14	○	○	○	○							
15	○	○	○	○	○						
16	○	○	○	○	○	○					
17	○	○	○	○	○	○					
18	○	○	○	○	○	○					
19	○	○	○	○	○	○					
20	○	○	○	○	○	○					
21	○	○	○	○	○	○					
22	○	○	○	○	○	○					
23	○	○	○	○	○	○					
24	○	○	○	○	○	○	○				
25		○	○	○	○	○	○				
26		○	○	○	○	○	○				
28		○	○	○	○	○	○				
30		○	○	○	○	○	○				
32		○	○	○	○	○	○				
40				○	○	○	○	○			

# MS ダブルピッチ軸穴加工付スプロケット

MS2040R	25	30	35		
MS2040RB 10	○	○	○		
MS2040RB 11	○	○	○		
MS2040RB 12	○	○	○		
MS2040RB 13	○	○	○		
MS2040RB 14	○	○	○		
MS2040RB 16	○	○	○		

MS2050R	25	30	35	40	
MS2050RB 10	○	○	○	○	
MS2050RB 11	○	○	○	○	
MS2050RB 12	○	○	○	○	
MS2050RB 13	○	○	○	○	
MS2050RB 14	○	○	○	○	
MS2050RB 15	○	○	○	○	
MS2050RB 18	○	○	○	○	
MS2050RB 20	○	○	○	○	

MS2060R	30	35	40	45	
MS2060RB 10	○	○	○	○	
MS2060RB 11	○	○	○	○	
MS2060RB 12	○	○	○	○	
MS2060RB 13	○	○	○	○	
MS2060RB 16	○	○	○	○	
MS2060RB 20	○	○	○	○	

MS2080R	30	35	40	45	
MS2080RB 11	○	○	○	○	
MS2080RB 12	○	○	○	○	

MS2040S	20	25	30	35	40
MS2040SB 9 1/2	○	○	○	○	○
MS2040SB 10 1/2	○	○	○	○	○
MS2040SB 11 1/2	○	○	○	○	○
MS2040SB 12 1/2	○	○	○	○	○

MS2050S	20	25	30	35	
MS2050SB 9 1/2	○	○	○	○	
MS2050SB 10 1/2	○	○	○	○	
MS2050SB 11 1/2	○	○	○	○	
MS2050SB 12 1/2	○	○	○	○	

MS2060S	25	30	35	40	
MS2060SB 9 1/2	○	○	○	○	
MS2060SB 10 1/2	○	○	○	○	
MS2060SB 11 1/2	○	○	○	○	
MS2060SB 12 1/2	○	○	○	○	

MS2080S	30	35	40	45	
MS2080SB 9 1/2	○	○	○	○	
MS2080SB 10 1/2	○	○	○	○	
MS2080SB 11 1/2	○	○	○	○	
MS2080SB 12 1/2	○	○	○	○	

MS2100S	30	35	40	45	
MS2100SB 9 1/2	○	○	○	○	

SMS40

	12	15	16	17	18	19	20	22	24	25	28	30	
10	○	○	○										
11	○	○	○										
12	○	○	○	○									
13	○	○	○	○	○								
14	○	○	○	○	○	○							
15	○	○	○	○	○	○	○						
16	○	○	○	○	○	○	○	○					
17	○	○	○	○	○	○	○	○	○				
18	○	○	○	○	○	○	○	○	○	○			
19	○	○	○	○	○	○	○	○	○	○			
20	○	○		○	○	○	○	○	○	○	○		
21				○	○	○	○	○	○	○	○	○	
22				○	○	○	○	○	○	○	○	○	
23				○	○	○	○	○	○	○	○	○	
24				○	○	○	○	○	○	○	○	○	
25				○	○	○	○	○	○	○	○	○	
26					○	○	○	○	○	○	○	○	
28					○	○	○	○	○	○	○	○	
30					○	○	○	○	○	○	○	○	
32					○	○	○	○	○	○	○	○	
35					○	○	○	○	○	○	○	○	
36					○	○	○	○	○	○	○	○	
40					○	○	○	○	○	○	○	○	

SMS50

	20	22	24	25	28	30	32	35	38	40		
10	○	○										
11	○	○	○									
12	○	○	○	○								
13	○	○	○	○	○							
14	○	○	○	○	○	○						
15	○	○	○	○	○	○	○					
16	○	○	○	○	○	○	○	○				
17	○	○	○	○	○	○	○	○				
18	○	○	○	○	○	○	○	○	○			
19	○	○	○	○	○	○	○	○	○			
20	○	○	○	○	○	○	○	○	○			
21				○	○	○	○	○	○			
22	○			○	○	○	○	○	○			
23	○			○	○	○	○	○	○			
24	○			○	○	○	○	○	○			
25	○			○	○	○	○	○	○			
26	○			○	○	○	○	○	○			
28	○			○	○	○	○	○	○			
30	○			○	○	○	○	○	○			
32				○	○	○	○	○	○			
35				○	○	○	○	○	○			

SMS60

	20	22	25	28	30	32	35	38	40			
10	○	○	○									
11	○	○	○									
12	○	○	○									
13	○	○	○	○								
14	○	○	○	○								
15	○	○	○	○	○	○						
16			○	○	○	○	○					
17			○	○	○	○	○					